ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
14

Ward Name
Bagalakunte

Street ID
W0215, W0230, W0217, W0198, W0182, W0081, W0209, W

Street Name
NA, 14th Crs, Chowdeshwari Temple Rd, 16th Crs, Om Shakthi Lyt 3rd Crs, Om Shakthi Lyt 1st Crs, 2nd

Significant Landmark
Sidedahalli Village

Segment No.
14/C-W0215/S055912

Total Length (m)
992.09

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	420.88	77.503240	13.066673	77.499449	13.067486	Sidedahalli Main road	MHR Circle
2	155.62	77.503043	13.064911	77.502831	13.063520	Hesaragatta Main road	4th cross SR layout
3	54.66	77.503576	13.064455	77.503657	13.064943	Sidedahalli Main road	1st Main
4	86.45	77.503538	13.064391	77.503416	13.063619	1st Main	Hesaragatta Main road
5	74.05	77.503821	13.064359	77.503743	13.063694	Sidedahalli Main road	1st Main
6	200.43	77.504815	13.064306	77.502978	13.064493	Kirliskar Layout 1st Main	Ganapathi temple

Work Details

History of Road / Lane / Circles

Name of the Work
Restoration of Road cut portion done by BWSSB (For Water Line and Sanitory Line) in Sidedahalli Village ward no 14 Bagalagunte

Sanctioned Estimated Amount (Rs.)
10000000

Sanctioned Year
2019-20

Year
2019 - 2020

Type of Work
Others

Other Work Type
Restoration of Road cut portion

Tender
Tender

Work Details

Job No. / Work Code
014-19-000193

Work Order No.
EE/DD/WO/390/19-20

Work Order Date
23/08/2019

Period of Extention

Defect Liability Period From
23/08/2019

Defect Liability Period To
20/08/2020

Multiple road involved with the same Job No/ Work Code #
No

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0215, W0230, W0217, W0198, W0182, W

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು

Scanned by CamScanner

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Yogesh (Professional global Infrastructure Pvt Ltd		9227865.00
Phone No.	**E-Mail ID**	
9845400303		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Umesh
Date of Inspection	**Remarks**	
19/11/2019		

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Segment End		Location was not determined.
Segment Start		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: DASARAHALLI Ward No: 14 Ward Name: Bagalakunte Street ID: W0215, W0230, W0217, W0198,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte

Street ID	Street Name	Significant Landmark
W0215, W0230, W0217, W0198, W0182, W0081, W0209, W	NA, 14th Crs, Chowdeshwari Temple Rd, 16th Crs, Om Shakthi Lyt 3rd Crs, Om Shakthi Lyt 1st Crs, 2nd	Sidedahalli Village

Segmont No.	Total Length (m)
14/C-W0215/S055912	992.09

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	420.88	77.503240	13.066673	77.499449	13.067486	Sidedahalli Main road	MHR Circle
2	155.62	77.503043	13.064911	77.502831	13.063520	Hesaragatta Main road	4th cross SR layout
3	54.66	77.503576	13.064455	77.503657	13.064943	Sidedahalli Main road	1st Main
4	86.45	77.503538	13.064391	77.503416	13.063619	1st Main	Hesaragatta Main road
5	74.05	77.503821	13.064359	77.503743	13.063694	Sidedahalli Main road	1st Main
6	200.43	77.504815	13.064306	77.502978	13.064493	Kirliskar Layout 1st Main	Ganapathi temple

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Restoration of Road cut portion done by BWSSB (For Water Line and Sanitory Line) In Sidedahalli Village ward no 14 Bagalagunte	10000000	2019-20

Year	Type of Work	Other Work Type
2019 - 2020	Others	Restoration of Road cut portion

Tender	Work Details	Job No. / Work Code
Tender		014-19-000193

Work Order No.	Work Order Date	Period of Extention
EE/DD/WO/390/19-20	23/08/2019	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
23/08/2019	20/08/2020	No

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0215, W0230, W0217, W0198,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner